



TERMINATION POINTS				
		CONNECTIONS		
POS.	DESCRIPTION	SIZE	RATING CLASS	FLANGES ACCORDING TO ANSI B 16.5
50	UNTREATED CRUDE OIL INLET FROM HEATER	4''	150LBS	X
51	TREATED CRUDE OIL OUTLET	3''	150LBS	X
52	RETURN OF UNTREATED CRUDE OIL	3''	150LBS	X
53	EFFLUENT WATER	1/2''	PN16	X
54	OILY SLUDGE OUTLET	2''	150LBS	X
55	VENT	2''	150LBS	
56	NITROGEN	1/2''	150LBS	X
58	COMPRESSED AIR	1/2''	150LBS	X
59	WATER INLET	1''	150LBS	X

DO NOT DISCHARGE THE OILY SLUDGE INTO THE PUPLIC SEWAGE SYSTEM!

COUNTER FLANGES, GASKETS, BOLTS AND NUTS ARE INCLUDED IN THE SCOPE OF SUPPLY

THE VENT AIR CONTAINS OIL MIST AND VAPORS.
EACH VENTILATION PIPE (CONNECTION 15) HAS TO BE INDIVIDUALLY ROOTED OUTSIDE THE BUILDING.

INSULATION: OIL PIPES:
PIPES AND VALVES WILL BE INSULATED

A HOIST SHOULD BE INSTALLED ABOVE THE SEPARATOR SO THAT
THE HEAVY BOWL PARTS CAN BE HANDLED MORE EASILY.
THE HOIST SHOULD BE MOUNTED ON A RUNNING RAIL SO THAT
BOWL PARTS CAN BE MOVED FROM SEPARATOR TO A WORKBENCH.
Um die schweren Trommelteile besser handhaben zu können, wird
empfohlen, über dem Separator ein Hebezeug anzubringen.
Das Hebezeug soll an einer Laufschiene befestigt sein, so daß
die Trommelteile auf einem Arbeitstisch abgesetzt werden können.





MAINTENANCE AREA
Wartungsfläche

EXAMPLE FOR TRANSPORTATION!



ONLY FOR INFORMATION
PRELIMINARY

FOR OPERATION OF THE EQUIPMENT PLEASE NOTE
THE RESPECTIVE LOCAL SAFETY REQUIREMENTS

SUBJECT TO TECHNICAL MODIFICATIONS

Revision	Description of Revision	Rev.-Date	Rev.-Name
Client	RMNTK		
Location	Krasnodar	Country Russia	
Revision proof is electronically stored	Copyright reserved We reserve all rights on this drawing.	CAD-Drawing	Last modified on 25.09.2012 / Last modified by GOEBYC
Created: Date 12.09.2012 / Name GOEMUC	GEA Westfalia Separator GmbH D-59302 Oelde	Description: 2151_30001747_RMNTK Layout Drawing Crude Oil Separator Double Unit OCU 2 x OSE 80-01-537	Drawing-No.: Q30001747-9938-LAY003
Checked			Scale 1:10 / Sheet 01 / Sheets 01 / Size A0
Approved			