


Techn
Aero



Specific
ing Systems,

Single Phase

Single phase
GPO is not
circuit breaker must be fitted.

Three Phase Power

Long vacuum tables are normally fitted with three phase pumps normally have three phase motors. Single phase motors are available, and where power is limited, several smaller vacuum pumps may be fitted. Three phase pumps are normally 4.2 - 5 KW and require a 10 amp circuit per pump. Although pumps seldom draw their rated current when used on vacuum tables, they are high voltage, high current devices and the associated switch gear should be wired and commissioned by suitably qualified electricians to suit local requirements. Aeronaut do not offer this service.

Each vacuum pump needs to be provided with a motor starter switch, mounted at the home end of the vacuum table. Aeronaut do not offer this service as we do not have suitably qualified personnel.

Wiring

The electrical supply and air connections are best run vertically down to the rear right hand side of the vacuum table to an isolator.

Aeronaut Automation Pty Ltd
44-46 Ross Street, Ross 3572 NSW, Australia
Phone: 012 442 8888 Fax: 012 442 8899 Email: info@aironaut.com.au